

Directions – Rust Buster

Read the product SDS carefully before handling this product.

Coverage:

Heavy rusted surfaces – 12 to 15 sqm/L.

Light rusted surfaces – 20 to 25 sqm/L

Sound painted surfaces – 30 sqm/L

Preparation:

1. Surface should be dry, free from grease, mill scale, loose rust and flaky paint.
2. For severe rusting, clean steel with sand, soda or water blasting.
3. Remove mill scale by pickling compound or blasting.

Application:

1. Immediately before use, stir until a uniform consistency is achieved.
2. Apply light coats using a brush, roller or airless spray gun.
3. Apply second coat after approximately 2 hours.
4. Apply a third coat if the dried second coat is not glossy.

Clean up: Mineral turpentine or paint thinners.

Drying time: Allow 24 hours before overpainting.

Note: Please see the Technical Data Sheet on our website for full details.