



Dislodge

Degreasing additive for raising flash point

Concentrated degreaser additive, contains no caustics, acids or creosote materials. Not classed as flammable as flash point is above 65°C. Raises the flashpoint of most solvents: improved safety with hot machinery. Makes solvents emulsify in water: improved rinsing. Increases solvent penetration: better cleansing and reduced residue.

★ AQIS-approved Category 3 general cleaner type C

1LT

Best before Dec 2021
1234567

D I S - X U - 9 - 1 0 0 - D M - 0 0 1 - L T M



Directions for use:

Dilution:

Motors, running gear and the like:

- with heavy grease and oil build-up: 1 part to 3 parts hydrocarbon solvent.
- with low grease and oil build-up or for soaking parts: 1 part to 10 parts hydrocarbon solvent.

Removing grease and oil from concrete floors and the like: 1 part to 3 parts hydrocarbon solvent.

Removing pre-delivery wax: 1 part to 20 parts hydrocarbon solvent.

Cleaning motors, running gear, concrete floors and the like:

1. Spray onto the surface to be cleaned.
2. Allow to dwell for 5 minutes.
3. Agitate with a brush or broom if required.
4. Thoroughly rinse with water. Preferably use a pressure washer.

Removing pre-delivery wax:

1. Apply with a cloth or spray and wipe.
2. Rinse with a pressure washer.

Note: Before using with painted surfaces, we recommend testing in an inconspicuous area first.